


ILAS

Level indicator with breather

- ▶ O-ring version for smooth holes.
- ▶ Large chamber with cut perpendicular to the axis protected by its cover of galvanized steel that keeps out foreign bodies and vents internal pressure.
- ▶ Built-in dipstick.
- ▶ Also available in various min. and max. notches and lengths.

[PRINTING NOTES](#)
[PRINT](#)

TYPE	CODE	O - R	h	p	l	$\varnothing f^{H11}$	g	d
ILAS1	1PISA10A	OR 115	18	9	170	17	5	22
ILAS2	1PISA20A	OR 119	19	9	170	20	5	26
ILAS3	1PISA30A	OR 3081	21	11	170	25	5	30
ILAS4	1PISA40A	OR 3100	26	14	200	30	5	38
ILAS5	1PISA50A	OR 4112	30	14	200	35	5	50



the safety of metal